Under Review Notification

Raised By: VANESSA MOREL Product #: DART TOOLING EUROCOPTER

Date: 17.12.14 Product Name: INPUT FLANGE SEAL EXCHANGE

		"Y" or "N" Required for Each Part Do not leave blank								
Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	HOLD SHIPMENT	Red Tag/Quarantine Stock	Advise Customers	Stop Production	Re-Work Stock	IPP Under Review	Product Specifications Under Review ("Bluefiles")	Reserved ECN Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
RBEM632V3009103	RBEM632V3009103 REV 1	Υ	Ν	N	N	N	Υ	Υ	17-743	WAIT FOR PART BEFORE SHIPPING

Description of Issue:

PART MISSING

MISSING PART IN RBEM632V3009126 ASSY, DIVIATION HAVE BEING SIGNED TO PRODUCE THIS PART AND ADD IT TO THE KIT BEFORE SHIPPING

Distribution:

VP Operations
Director of Operations
Director Quality Assurance
Director of Engineering

Chief Engineer
Engineering Project Managers
Engineering Clerk
Customer Support Manager

Production Engineers
Production Planners
Purchasing Manager
Technical Support

Product Manager - Solutions Provider